
**Advanced Gamma Spectroscopy
Course Outline**

1. INTRODUCTION

1.1. *Program Philosophy*

1.2. *Program Components*

2. GAMMA-RAY DETECTION PRINCIPLES

2.1. *Semiconductor Theory*

2.2. *Semiconductor Characteristics*

2.3. *Semiconductor Detectors*

3. SEMICONDUCTOR DETECTOR SYSTEMS

3.1. *Pulse Height analysis*

3.1.1. *Signal and Noise*

3.1.2. *Multichannel Pulse Height Analysis*

3.2. *Detector System Components*

3.2.1. *Overview*

3.2.2. *Preamplifiers*

3.2.3. *Bias Supplies*

3.2.4. *Amplifiers*

3.2.5. *Analog-to-Digital Converters*

3.2.6. *Multichannel Analyzers*

3.3. *System Dead Time*

4. GAMMA-RAY INTERACTIONS AND SPECTRAL FEATURES

4.1. *Interaction Mechanisms*

4.2. *The Gamma-Ray Spectrum*

4.3. *Detector Geometry Effects*

4.4. *Spectral Peak Characteristics*

4.4.1. Introduction

4.4.2. Peak Parameters

4.4.3. Peak Shape Implications

4.5. *General Spectral Features*

4.5.1. Introduction

4.5.2. Primary Versus Secondary Spectral Features

4.5.3. Secondary Features - Detector Interactions

4.5.4. Secondary Features - Shielding Interactions

4.5.5. Summing Features

4.6. *Spectral Background Effects*

4.6.1. Signal Sources

4.6.2. Gamma-Ray Features

4.6.3. Shielding Materials

4.6.4. Spectroscopy System Background Evaluation

5. GAMMA-RAY SPECTROSCOPY SYSTEM CALIBRATIONS

5.1. *Introduction*

5.2. *First Order Energy Calibrations*

5.2.1. *Technique Basis*

5.2.2. *Mathematical Basis*

5.2.3. *Computer Assisted Calibration*

5.3. *Second Order Energy Calibrations*

5.4. *Efficiency Calibrations*

5.4.1. *Introduction*

5.4.2. *Calibration Curves*

5.4.3. *Mathematical Treatment of Efficiency Curves*

5.4.4. *Analysis of High Activity Samples*

5.4.5. *Detector*

5.4.6. *Preamplifier*

5.4.7. *Amplifier*

5.4.8. *ADC and MCA*

5.4.9. *Dead Time Corrections*

5.4.10. *Equipment Testing*

6. POWER PLANT SOURCES OF GAMMA-RAY ACTIVITY

6.1. *Introduction*

6.2. *Coolant Activation Products*

6.3. *Delay Count Program*

6.4. *Corrosion and Wear Products*

6.5. *Fission Products*

6.5.1. *The Fission Process*

6.5.2. *Tramp Uranium*

6.5.3. *Fission Gases*

6.5.4. *Radioiodines*

6.5.5. *Soluble Fission Products*

6.5.6. *Insoluble Fission Products*

6.6. *Transuranics*

6.7. *Tritium*

6.8. *Power Plant Activity Levels*

6.8.1. *Nuclide Production*

6.8.2. *Changes in General Activity Levels*

6.8.3. *Fission Product Activity Levels*

7. *SOFTWARE ASSISTED SPECTRAL ANALYSIS*

7.1. *Channel-by-Channel Data Reduction*

7.1.1. *Introduction*

7.1.2. *Spectral Smoothing*

7.2. *Determination of Peak Location*

7.2.1. *Peak Location Methods*

7.2.2. *First Derivative Testing*

7.2.3. *Second Difference Method*

7.3. *Determination of Peak Intensity*

7.3.1. Introduction

7.3.2. Nonfitted Techniques

7.3.3. Fitting Techniques

7.4. *Nuclide Identification Techniques*

7.4.1. Introduction

7.4.2. Nuclide Library Format and Design

7.4.3. Library Guidelines for Matrix Loaded Analysis

7.4.4. Library Guidelines for key Line Analysis

7.5. *Validation of Nuclide Library Entries*

7.5.1. Introduction

7.5.2. Software Tests

7.5.3. Half-Life Ratio Test

7.5.4. Abundance Limit Test

7.5.5. Limitations to Library Testing

7.5.6. Use of Decay Time to Lessen Spectral Interference

7.5.7. Delay Count Program

7.5.8. Reporting Results

7.5.9.

8. SPECTRAL VERIFICATION PRACTICES

8.1. *Reference Sources*

8.1.1. Overview

- 8.1.2. Chart of the Nuclides
- 8.1.3. Table of Isotopes
- 8.1.4. Energy Ordered Gamma-Ray Listings
- 8.2. *Assessment of Secondary Spectral Features*
- 8.3. *Interference Correction Techniques*
 - 8.3.1. Correction Criteria
 - 8.3.2. Calculational Techniques
- 8.4. *Visual Analysis Techniques*
 - 8.4.1. Introduction
 - 8.4.2. Evaluation of Channel-by-Channel Data
 - 8.4.3. Channel-by-Channel Plotting Techniques
- 8.5. *Verification of Power Plant Nuclides*
 - 8.5.1. Iodine Activity Trends
 - 8.5.2. Cesium Levels
 - 8.5.3. Insoluble Fission Product Levels
- 8.6. *Half-Life Studies*
 - 8.6.1. Introduction
 - 8.6.2. General Technique
 - 8.6.3. Decay Curve Analysis
- 8.7. *Parent-Daughter Equilibrium*
 - 8.7.1. General Concepts
 - 8.7.2. Maximum Time

8.8. *Statistical Considerations of Small Spectral Peaks*

8.8.1. LLD and Critical Level

8.8.2. Measurement Uncertainties

8.8.3. Propagation of Uncertainties

8.9. *Quality Control Techniques*

8.9.1. Quality Parameters

8.9.2. Control Chart Guidelines

8.9.3. Control Chart Limitations

8.9.4. Analysis Specific quality Control Techniques

8.10. *Sampling*

8.10.1. Rheodyne Samples

8.10.2. Crud Samples

8.10.3. Liquid Samples

8.10.4. Filtrate Samples

8.10.5. Stripped Gas Samples